



Zavore na elektromotorjih so tovarniško nastavljene na mehko zaviranje (počasno).

Pri 400V usmerniku je potrebno 1 in 2 vezati med fazi L1 in L2.

The brakes mounted on the electricmotors are originally set for soft braking (slowly).

At the 400V rectifire must be pin 1 and 2 connected between phase L1 and L2.